

TIP OF THE WEEK

FOR IMMEDIATE RELEASE

Date: August 14, 2025

Contact: Sheriff Adam Shanks

541-265-0652

<u>lcsheriff@co.lincoln.or.us</u>

ODOT WORK ZONES

As you gear up for that final summer road trip or just make your way home from work, you may run into roadwork and traffic delays. That may mean reduced speed limits and traffic delays in work zones. Did you know 4 out of 5 work zone crash victims are NOT the workers? It is actually the drivers and their passengers traveling through the work zone areas. Inattention and speed are the most common causes of work zone crashes.

Work zones are dangerous for everyone even when workers are not visible. That is why Oregon Department of Transportation (ODOT) lowers the speed limits in work zones. Exceeding work zone speed limits can be especially hazardous for numerous reasons:

- Traffic patterns may change day to day
- Roads may be rough, uneven or covered with debris
- Temporary lanes may be narrow with abrupt edges
- Roadside equipment may obstruct views

Commuters are often caught off guard by work zone hazards. Distracted driving and driving over the speed limit reduces the necessary reaction time to avoid a crash. When you see orange signs, cones, and barrels on the roadway, PAY EXTRA ATTENTION! Those are your clues to be prepared for unexpected obstacles and stopped or slowing cars. Slow down, stay alert, and avoid distractions.

For more information about work zone safety, go to ODOT's website at: http://www.oregon.gov/ODOT/Safety/Pages/Work-Zone.aspx

For more information and tips visit our website at <u>www.lincolncountysheriff.net</u> and like us on Facebook at Lincoln County Sheriff's Office – Oregon.

###